

Detail: Contactor Docking Area S01000T
 (View from tester side)

no threads or holes allowed
 inside the hatched area

Level of Contactor
 Lock Screws
 (900mm above bottom)

Position of Contactor
 Guide Pins (ø8mm)

Position of Contactor
 Lock Screws (M8)

Deicing air
 exhausts

